

FIGURE 1




FIGURE 2A




FIGURE 2B

FIGURE 3

300

200




FIG. 4




FIGURE 4




FIGURE 5




FIGURE 6A




FIGURE 6B

700





FIGURE 7

05031216 061501

TESTING ATTENTION

IRTP1 490a



480

Fig 8

09381216 061501




Fig 9

TEST SET 471





Fig 10



422

FIGURE 11

09881216, 061501




FIGURE 12

05001216 061501




FIGURE 13






FIGURE 14




to 1402



1406

to 1412

to 1408



REF DWG A4206

RS-232 SERIAL CABLE # 73-XXXX

SERIAL CABLE # 73-XXXX

"BASIC" RS-232 PORT


"SMART" RS-232 PORT

TRIPP LITE SMART-3000

SVOC ADAPTER

SVOC ADAPTER

1410



NOTE: 36" CAT 6 PATCH CABLE USED TO UPLINK FROM F3324 TO F3106-NA

FIGURE 16

**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ BLACK BORDERS
- ☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
- ☐ FADED TEXT OR DRAWING
- ☒ BLURRED OR ILLEGIBLE TEXT OR DRAWING
- ☐ SKEWED/SLANTED IMAGES
- ☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
- ☐ GRAY SCALE DOCUMENTS
- ☐ LINES OR MARKS ON ORIGINAL DOCUMENT
- ☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
- ☐ OTHER: _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.